DEPARTMENT OF TRANSPORTATION
Federal Aviation Administration
14 CFR Part 33
[Docket No. NE130; Special Conditions No. 33-008-SC]
Special Conditions: Pratt and Whitney Canada Model PW210S Turboshaft Engine

Correction

In rule document 2011-14113 appearing on pages 33981-33982 in the issue of Friday, June 10, 2011, make the following correction:

On page 33981, in the first column, in the heading, Special Conditions No. "33-008-SCI" should read "33-008-SCI".

[FR Doc. C1-2011-14113 Filed 01/12/2012 at 8:45 am; Publication Date: 01/13/2012]